

**BLADE REPAIR CAPABILITIES****709-0103-01-XXX AW109 MAIN ROTOR BLADE**

- Blade Body Skin Patch
- Erosion Shield Replacement
- Lap Plate Replacement (Tip Splice Cover)
- Main Bushing Replacement
- Major Skin Repair
- Refinish and Balance
- Root Closure Replacement
- Root Fairing Replacement
- Skin Panels and Fairings Repair
- Tip Cap Replacement / Fiberglass, Metal
- Trailing Edge Fairing Replacement
- Trim Tab Replacement

**709-0160-48-101 AW109 TAIL ROTOR BLADE****109-8132-01 AW109 METAL TAIL ROTOR BLADE**

- Attachment Bushings Replacement
- Elastomeric Bearings Replacement
- Refinish and Balance
- Skin Patch
- Skin Repairs
- Tip Cover Replacement

For additional information, contact us or visit [www.bh.com/blade-repair](http://www.bh.com/blade-repair)

**CONTACT YOUR LOCAL BELL HELICOPTER BLADE FACILITY TO SCHEDULE BLADE REPAIR(S)****BELL HELICOPTER**

580-A St. Etienne Road  
Broussard, LA 70518  
United States

Phone: 337.839.2119  
Email: [bladerepair@bh.com](mailto:bladerepair@bh.com)  
Repair Station: R8DR713Y

**ROTOR BLADES LIMITED**

Unit 5 B, Crusader Park  
Warminster, Wiltshire BA12 8BT  
United Kingdom

Phone: +44.1985.847040  
Email: [repairs@rotor-blades.com](mailto:repairs@rotor-blades.com)  
Repair Station: UK.145.01122

**RBI HAWKER LTD.**

LIU FZS1 BD06/07  
JAFZ South, Dubai UAE  
P.O. Box 16784 Dubai

Phone: +971.4.886.0144  
Fax: +971.4.886.0145  
Email: [info@rbihawker.com](mailto:info@rbihawker.com)  
Repair Station: 6RBY351C (FAA),  
145.0314 (EASA)

BELLHELICOPTER.COM



© 2017 Bell Helicopter Textron Inc. All registered trademarks are the property of their respective owners. The information herein is general in nature and may vary with conditions. Individuals using this information must exercise their independent judgment in evaluating product selection and determining product appropriateness for their particular purpose and requirements. For performance data and operating limitations for any specific mission, reference must be made to the approved flight manual. Bell Helicopter Textron Inc. makes no representations or warranties, either expressed or implied, including without limitation any warranties of merchantability or fitness for a particular purpose with respect to the information set forth herein or the product(s) and service(s) to which the information refers. Accordingly, Bell Helicopter Textron Inc. will not be responsible for damages (of any kind or nature, including incidental, direct, indirect, or consequential damages) resulting from the use of or reliance on this information. Bell Helicopter Textron Inc. reserves the right to change product designs and specifications without notice. BLADE REPAIRS AW109 170403-R04 EN