

BLADE REPAIR CAPABILITIES

407-015-001-XXX BELL 407 MAIN ROTOR BLADE

406-015-001-XXX BELL OH-58D MAIN ROTOR BLADE

- | | | |
|---|--|--|
| <ul style="list-style-type: none"> • Abrasion Strip Replacement • Erosion Shield Replacement • Flight Performance Wedging • Forward Pocket Drain Hole Addition & Pocket Rework Procedures • Fretting Pad Replacement | <ul style="list-style-type: none"> • Lightning Strike Modification / Repair • Main Bushing and Liner Replacement • Major Skin Repair • Polyurethane Leading Edge Strip Replacement • Refinish and Balance | <ul style="list-style-type: none"> • Repair Damaged or Voided Bridge Ply • Root Closure Replacement • Skin Repair on Tracer Strands • Supplemental Abrasion Strip Install • Trailing Edge Spar Repair • Trim Tab Replacement |
|---|--|--|

407-010-101-XXX BELL 407 YOKE

- | | | |
|---|---|--|
| <ul style="list-style-type: none"> • Yoke • Yoke Buffer Pad Replacement • Yoke Bushing Replacement | <ul style="list-style-type: none"> • Yoke Center Buffer Bore Replacement • Yoke ID Tag Replacement • Yoke Refinish | <ul style="list-style-type: none"> • Yoke Skin Repair |
|---|---|--|

406-016-100-XXX BELL 407 TAIL ROTOR BLADE

- | | | |
|--|--|--|
| <ul style="list-style-type: none"> • Abrasion Strip Replacement • Erosion Shield Replacement | <ul style="list-style-type: none"> • Refinish and Balance • Skin Repairs | <ul style="list-style-type: none"> • Supplemental Abrasion Strip Install • Tip Block Replacement |
|--|--|--|



For additional information, contact us or visit www.bh.com/blade-repair

CONTACT YOUR LOCAL BELL HELICOPTER BLADE FACILITY TO SCHEDULE BLADE REPAIR(S)

BELL HELICOPTER

580-A St. Etienne Road
 Broussard, LA 70518
 United States
 Phone: 337.839.2119
 Email: bladerrepair@bh.com
 Repair Station: R8DR713Y

ROTOR BLADES LIMITED

Unit 5 B, Crusader Park
 Warminster, Wiltshire BA12 8BT
 United Kingdom
 Phone: +44.1985.847040
 Email: repairs@rotor-blades.com
 Repair Station: UK.145.01122

RBI HAWKER LTD.

LIU FZS1 BD06/07
 JAFZ South, Dubai UAE
 P.O. Box 16784 Dubai
 Phone: +971.4.886.0144
 Fax: +971.4.886.0145
 Email: info@rbihawker.com
 Repair Station: 6RBY351C (FAA),
 145.0314 (EASA)

BELLHELICOPTER.COM



© 2017 Bell Helicopter Textron Inc. All registered trademarks are the property of their respective owners. The information herein is general in nature and may vary with conditions. Individuals using this information must exercise their independent judgment in evaluating product selection and determining product appropriateness for their particular purpose and requirements. For performance data and operating limitations for any specific mission, reference must be made to the approved flight manual. Bell Helicopter Textron Inc. makes no representations or warranties, either expressed or implied, including without limitation any warranties of merchantability or fitness for a particular purpose with respect to the information set forth herein or the product(s) and service(s) to which the information refers. Accordingly, Bell Helicopter Textron Inc. will not be responsible for damages (of any kind or nature, including incidental, direct, indirect, or consequential damages) resulting from the use of or reliance on this information. Bell Helicopter Textron Inc. reserves the right to change product designs and specifications without notice. BLADE REPAIRS 407 SERIES / OH-58D 170403-R01 EN