

**BLADE REPAIR CAPABILITIES**

**214-015-500-XXX BELL 214 MAIN ROTOR BLADE**

**214-015-300-XXX BELL 214ST MAIN ROTOR BLADE**

- |  |   |  |
|--|---|--|
| <ul style="list-style-type: none"> <li>• Abrasion Strip Replacement</li> <li>• Drag Bushing Replacement</li> <li>• Erosion Shield Replacement</li> <li>• Flight Performance Wedging</li> <li>• Grip Pad Replacement</li> <li>• Main Bushing Replacement</li> </ul> | <ul style="list-style-type: none"> <li>• Major Skin Repair</li> <li>• Outboard Abrasion Strip Replacement</li> <li>• Refinish and Balance</li> <li>• Root Closure Replacement</li> <li>• Splice Cover Replacement</li> <li>• Supplemental Abrasion Strip Install</li> </ul> | <ul style="list-style-type: none"> <li>• Supplemental Tip Shoe Cover Install</li> <li>• Tip Closure Replacement</li> <li>• Tip Shoe Replacement</li> <li>• Trailing Edge Repair</li> <li>• Trim Tab Replacement</li> </ul> |
|--|---|--|

**214-015-750-XXX BELL 214 TAIL ROTOR BLADE**

**214-015-700-XXX BELL 214 TAIL ROTOR BLADE**

- |   |   |   |
|---|---|---|
| <ul style="list-style-type: none"> <li>• Refinish and Balance</li> <li>• Retention Bushing Replacement</li> </ul> | <ul style="list-style-type: none"> <li>• Skin Repairs</li> <li>• Supplemental Abrasion Strip Install</li> </ul> | <ul style="list-style-type: none"> <li>• Tip Closure Replacement</li> </ul> |
|---|---|---|



For additional information, contact us or visit [www.bh.com/blade-repair](http://www.bh.com/blade-repair)

**CONTACT YOUR LOCAL BELL HELICOPTER BLADE FACILITY TO SCHEDULE BLADE REPAIR(S)**

**BELL HELICOPTER**

580-A St. Etienne Road  
 Broussard, LA 70518  
 United States  
 Phone: 337.839.2119  
 Email: [bladerrepair@bh.com](mailto:bladerrepair@bh.com)  
 Repair Station: R8DR713Y

**ROTOR BLADES LIMITED**

Unit 5 B, Crusader Park  
 Warminster, Wiltshire BA12 8BT  
 United Kingdom  
 Phone: +44.1985.847040  
 Email: [repairs@rotor-blades.com](mailto:repairs@rotor-blades.com)  
 Repair Station: UK.145.01122

**RBI HAWKER LTD.**

LIU FZS1 BD06/07  
 JAFZ South, Dubai UAE  
 P.O. Box 16784 Dubai  
 Phone: +971.4.886.0144  
 Fax: +971.4.886.0145  
 Email: [info@rbihawker.com](mailto:info@rbihawker.com)  
 Repair Station: 6RBY351C (FAA),  
 145.0314 (EASA)

BELLHELICOPTER.COM |

© 2017 Bell Helicopter Textron Inc. All registered trademarks are the property of their respective owners. The information herein is general in nature and may vary with conditions. Individuals using this information must exercise their independent judgment in evaluating product selection and determining product appropriateness for their particular purpose and requirements. For performance data and operating limitations for any specific mission, reference must be made to the approved flight manual. Bell Helicopter Textron Inc. makes no representations or warranties, either expressed or implied, including without limitation any warranties of merchantability or fitness for a particular purpose with respect to the information set forth herein or the product(s) and service(s) to which the information refers. Accordingly, Bell Helicopter Textron Inc. will not be responsible for damages (of any kind or nature, including incidental, direct, indirect, or consequential damages) resulting from the use of or reliance on this information. Bell Helicopter Textron Inc. reserves the right to change product designs and specifications without notice. BLADE REPAIRS 214 170403-R05 EN