

INSPECTION SERVICES



INSPECTION SERVICES

ESTABLISHED IN 2007, RBL IS A TEXTRON COMPANY AND AUTHORIZED BELL SERVICE CENTRE.

We are a UK Civil Aviation Authority (CAA) and European Aviation Safety Agency (EASA) approved Part 145 Maintenance Facility located in Warminster, England, UK. We specialize in the inspection maintenance and repair of your composite and metal rotor blades.

INSPECTION SERVICES

Every rotor blade entering our facility is fully examined visually and by using proven NDI techniques. This identifies all visible and invisible damage or delamination within the blade structure.

Accurate balancing of your rotor blade will decrease the number of rotor track and balance flights. RBL's digital balancing equipment provides span wise as well as chord wise static balancing, all according to OEM data or Bell master blades.

INSPECTION AFTER:

- Major overspeed
- Sudden stoppage
- Hard landing and after
- Lightning Strike

SERVICES:

- Visual
- NDI
- Borescope inspection
- Leak check inspection

FOR MORE INFORMATION AND AN INITIAL QUOTE

Repairs_rbl@bellflight.com | +44 (0) 1985 847 040



OUR CAPABILITIES COVER THE FOLLOWING MAKES AND MODELS:

- All Bell Main and Tail Rotors
- All Agusta Bell Main and Tail Rotors
- Van Horn Tail Rotors
- Bell 407 / 427 / 429 / 430 Yoke Repair

3-YEAR, 2,000-HOUR WARRANTY

Stay confident with a 3-year, 2,000-hour warranty backed by the industry leader in customer support.

