



PREVENTATIVE MAINTENANCE



PREVENTATIVE MAINTENANCE

Erosion Protection | Bell 206, 212, 407, 412, 427, 429 and 505

**ESTABLISHED IN 2007, RBL IS A
TEXTRON COMPANY AND AUTHORISED
BELL SERVICE CENTRE.**


We are a UK Civil Aviation Authority (CAA) and European Aviation Safety Agency (EASA) approved Part 145 Maintenance Facility located in Warminster, England, UK. We specialize in the inspection maintenance and repair of your composite and metal rotor blades.

3-YEAR, 2,000-HOUR WARRANTY

Stay confident with a 3-year, 2,000-hour warranty backed by the industry leader in customer support.

OEM-APPROVED SUPPLEMENTAL STRIPS

When operating your aircraft in high erosion environments, RBL can install inexpensive supplemental erosion strips to protect your blade. These durable nickel strips ease maintenance, reduce repair cost and assist in meeting life limits.



OEM-APPROVED PAINT LINE SEALANT

Paint line sealant can be applied to all Bell Main and Tail rotor blades to prevent leading edge paint erosion.

FOR MORE INFORMATION & AN INITIAL QUOTE
Repairs_rbl@bellflight.com | +44 (0) 1985 847 040